Darrington / Darrington Municipal / 1S2



Communications

Navigation

CTAF122.9
PCLCTAF (For MIRL)

Elevation 553' MSL

Longitude W 121° 36.61′



Services

Fuel None

Fly Washington Passport Program – Stamp located midfield, south of tie-down area; in metal box on north wall of beige hangars.

Notes

Unattended. Turbulent air on hot days. Closed when snow on runway. Taxiways marked with blue reflectors. MIRL 10-28 OTS indef.