## Morton / Strom Field / 39P



			4.0	
	∩mm	linic	ations	
•		иши	utions	

**Navigation** 

CTAF	122.9	
PCI	CTAF (For MIRI	& BCI

Elevation . . . . . 941' MSL

Longitude . . . . . W 122° 16.00′



## **Services**

Fuel ..... None

Fly Washington Passport Program – Stamp is in clear plastic box between first and second hangar on west end.

Note: Runway is short and narrow. Pavement is in poor condition. Land at your own risk.

Notes

Unattended. Displaced threshold Rwy 07 - 200' - 1610' avail. Displaced threshold Rwy 25 - 200' - 1610' available. Deer and elk on and in vicinity of runway.