

Eatonville / Swanson Field / 2W3



Communications

CTAF 122.9
 PCL 122.9 (For MIRL)

Navigation

Elevation 843' MSL
 TPA 1643' MSL (800' AGL)
 Runway 16/34; 2990'x36'; ASPH
 Lights Dusk-dawn, MIRL
 Latitude N 46° 52.30'
 Longitude W 122° 15.43'



Services

Fuel None

Fly Washington Passport Program - mailbox is in the information booth at the drive-in entrance to the airport on the NW corner. There is a flagpole near the booth. Gravel service road around RWY 16/34 is not available for aircraft operations. Please Read Chart Supplement For Details.

Notes

Right-hand traffic on runway 16. Watch for deer on airport. Buildings and roads close proximity to runway. Roads are not taxiways, aircraft must back taxi. On departure maintain runway heading until beyond runway threshold.