Port Townsend / Jefferson County International / ØS9



Communications

AWOS-3......119.025 CTAF/UNICOM 123.0

PCL CTAF (For MIRL)

Navigation

Elevation 110' MSL

Lights Dusk-dawn, MIRL

Latitude N 48° 03.23′

Longitude W 122° 48.64′



Services

Fuel 100LL (24-hour credit card fuel services)

Fly Washington Passport Program – Stamp located inside the visitor kiosk to the right of the Spruce Goose Cafe. Additional Bonus Stamp at Port Townsend Aero Museum, plus vintage airplanes!

Notes

Right-hand traffic on runway 09. Noise abatement procedures in effect, call airport manager at 360-385-0656. Tkf and ldg prohibited on turf next to rwy.