Renton / Renton Municipal / RNT



Communications	ivavigation
ATIS 126.95	Elevation 32' MSL
TWR124.7	TPA 1032' MSL (1000' AGL)
GND121.6	Runway 16/34; 5382'×200';
CTAF 124.7	ASPH-CONC-Grvd
UNICOM 122.85 and 122.95	Lights Dusk-dawn, NSTD, MIRL
PCL CTAF (For MIRL Rwy 16/34; REIL	Latitude N 47° 29.59′
Rwy 16/34 & twy lights)	Longitude W 122° 12.95′



Services

Fuel 100LL, Jet A, and Jet A+

Fly Washington Passport Program – Stamp located at the base of the tower, Airport Office.

Notes

Right-hand traffic on runway 34. Displaced threshold Rwy 16 - 300' - 5082' avail. Displaced threshold Rwy 34 - 340' - 5042' available. Seaplane base NW corner. Numerous flocks of birds. Noise abatement procedures contact arpt mgr. Be alert for Boeing production aircraft being towed across runway during hours when tower is closed. TPA west of fld is 1218' AGL due to terrain.